



TECHNICAL SERVICE BULLETIN

<b>NUMBER</b>	<b>SD-TSB-112122</b>			<b>TYPE</b>	<b>INFORMATION ONLY</b>			
<b>ROUTING</b>	INSTALL	X	SERVICE	X	SALES		PURCH	
<b>TITLE</b>	<b>3057918 - NEW LARGE SPREADER CONTROLLERS</b>							
<b>REV</b>	<b>A</b>			<b>ISSUED</b>	<b>11/21/2022</b>		<b>REVISED</b>	<b>8/9/2023</b>
<b>AFFECTS</b>	<b>PRO/SCH/MUNI/RTS/MID SERIES SPREADERS</b>							
<b>INFORMATION</b>	<p>In an effort to prevent future supply chain issues and continue to improve our products, two new controllers have been developed to replace/supplement the 3016934 spreader controller. These have improved functionality and are nearly drop in replacements.</p> <p>The only difference in installation is that there is NO ignition enable wire, and there is now an auxiliary light wire. Spreaders may contain any one of these three controllers.</p> <p>If the auxiliary light wire is accidentally connected to an ignition feed it should not cause damage, but it should be removed.</p> <p><b>THE PART NUMBER 3057918 is now the correct service PN and may be any of the three controllers shown below. We cannot guarantee the availability of a specific controller.</b></p> <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> <p>3016934</p> </div> <div style="text-align: center;"> <p>3046955</p> </div> <div style="text-align: center;"> <p>3049810</p> </div> </div>							
<b>INSTRUCTIONS</b>	No action needs to be taken.							