



<b>NUMBER</b>	TSB16-72	<b>TYPE</b>	INSTALLATION ALERT		
<b>TITLE</b>	16013002 VXF Hose Routing				
<b>REV</b>	-	<b>ISSUED</b>	8/10/2017	<b>REVISED</b>	-
<b>AFFECTS</b>	Lift Frame Assembly #16013002				
<b>INFORMATION</b>	During packing the hoses may have been routed incorrectly and pinched by the lift frame. A second set of clamps is being added to correct this issue.				
<b>DETECTION</b>	Inspect hoses for damage. Hoses should have two sets of clamps as shown below				

**CORRECTIVE ACTION**

Place 2nd set of clamps (#16111148) as shown 3" back from cross member of the A-frame. If the hoses (#16153120) were damaged in shipping they should be replaced. This repair should take no longer than 15 minutes.

