

## TECHNICAL SERVICE BULLETIN

| ь            | Buyers Turney                        | THE                     |  |
|--------------|--------------------------------------|-------------------------|--|
| NUMBER       | 16TSB-43                             | TYPE                    | OPERATION ALERT  |
| TITLE        | MD D2TM MOUNT INSTRUCTIONS           |                         |  |
| REV          | Α                                    | ISSUED                  | 12/28/2010 REVISED -   |
| AFFECTS      | 16015000 MD PLOW                     | 'S WITH DUA             | L PEDAL MOUNT SYSTEM   |
| INFORMATION  | COMMONALITY BETW FAILURE TO PROPERLY | EEN THE MD<br>MOUNT THE | AND HD/EX PLOWS HAVE TWO HOLES TO ALLOW FOR AND HD/EX PLOWS. THE EXTRA HOLE IS NOT FOR A LOCK PIPLOW CAN RESULT IN THE PLOW DISCONNECTING WHEN ACKING LOADS WHEN THE PINS ARE NOT FULLY EXTENDED.  |
| INSTRUCTIONS |                                      | _                       | OT PEDALS ARE TO BE INSTALLED AS SHOWN WHEN THE PLOW DULD BE FULLY EXTENDED WHENEVER THE PLOW IS ON THE  RETRACTING PIN IS FULLY EXTENDED  LOCK PIN GOES IN OUTSIDE OF FOOT PEDAL  THIS HOLE IS NOT USED  PEDAL SHOULD BE FOLDED ALMOST FLAT TO THE LIFT FRAME |