



TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-67			TYPE	SERVICE ALERT			
ROUTING	INSTALL	X	SERVICE		SALES		PURCH	
TITLE	WRONG CONTROLLER INCLUDED							
REV	A			ISSUED	11/12/2015	REVISED	-	
AFFECTS	SMALL NUMBER OF 1601100/16012000/16015000 LIFT FRAME KITS - HD/EX/TE/MD PLOWS							
INFORMATION	<p>SOME STRAIGHTBLADE PLOW LIFT FRAMES WERE PACKED WITH THE V-PLOW CONTROLLER (16161600). THIS PREVENTS THE PLOW FROM FUNCTIONING CORRECTLY.</p> <p>THE STRAIGHT BLADE CONTROLLER (16160600) HAS JUST THE DOGG HEAD ON THE CONTROLLER FACE.</p> <p>THE VPLOW CONTROLLER (16161600) HAS A "V" THROUGH THE DOGG HEAD.</p> <p>THE XP CONTROLLER (16162600) HAS AN "X" THROUGH THE DOGG HEAD.</p>							
DETECTION	THIS WOULD BE DETECTED AT FIRST PLOW OPERATION AFTER INSTALL.							
CORRECTION	CONTACT BPC CUSTOMER SERVICE FOR THE CORRECT CONTROLLER. THE STRAIGHT BLADE CONTROLLER IS 16160600.							