




TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-107			TYPE	APPLICATION ALERT				
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH		
TITLE	16071010 Headlight Adapter Mislabelling/Flickering								
REV	-			ISSUED	10/24/2023			REVISED	
AFFECTS	16071010 Headlight Adapter for 2019-2022 GM1500 and 2020-2023 GM2500/3500								
INFORMATION	<p>16071010 Headlight adapters shipped in 2022 and 2023 may have a label that says "16071070" on the individual harnesses. These harnesses ARE wired correctly and ARE 16071010 harnesses. The bags are labelled correctly - the labelling issue is on the individual harnesses.</p> <div style="text-align: center;">  </div> <p>There have also been complaints about flickering with these harnesses. This appears to be caused by some of the terminals not being properly retained in the housing. If any wires can be pulled from the housing, try to reseat them by pushing them in. If they do not "lock" into place, the harness should be replaced.</p>								
INSTRUCTIONS	<p>All stock has been corrected as of 10/25/2023. No action is required by the dealer on the labelling issue - but it is advised to mark the harnesses appropriately to avoid confusion once they are removed from the packaging.</p> <p>Any harnesses with terminals that are not "locking" in place may be replaced under warranty by contacting your dealer or Buyers Products Customer Service.</p>								