



TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-34	TYPE	INSTALLATION ALERT		
TITLE	GM S-10/SONOMA 16071150R INSTALLATION / FUSE BLOWING				
REV	A	ISSUED	10/30/2009	REVISED	-
AFFECTS	16071150R INSTALLATION FOR GM S-10/SONOMA W/DRL'S				
INFORMATION	<p>WE HAVE HAD INSTANCES OF THE 10A FUSE BLOWING ON GM S-10/SONOMA INSTALLS. THIS IS BELIEVED TO BE DUE TO THE WAY THE S-10/SONOMA IMPLEMENTS DRL'S. TESTING HAS SHOWN THE CURRENT DRAWING TO BE ~12A MAX.</p> <p>IF THE FUSE BLOWS, THE CONTROLLER AND LIGHTS WILL LOSE POWER.</p>				
INSTRUCTIONS	REPLACE THE 10A FUSE WITH A 15A FUSE				