



**TECHNICAL
SERVICE BULLETIN**

NUMBER	16TSB-98			TYPE	SERVICE ALERT			
ROUTING	INSTALL	X	SERVICE	X	SALES	X	PURCH	
TITLE	16062290 MOUNT, HD/EX/VX, RAM 2500/3500, 19+ INCORRECT PUSHBAR							
REV	A			ISSUED	1/13/2022		REVISED	
AFFECTS	SOME 16062290 SHIPPED BETWEEN 11/23/2021 AND 01/13/2022							
INFORMATION	<p>Some 16062290 mounts shipped between 11/23/2021 and 01/13/2022 may have been built with the wrong pushbar. The CORRECT pushbar (16062279) should be 39.25" long with rear tabs 30" apart as shown. The pushbar that may have been included is the correct length – but the rear tabs are 33.5" apart and should not be used.</p> <p>The diagram shows a side view of a pushbar with two vertical mounting tabs. Dimension lines indicate a total length of 4.375 REF, a distance of 30.000 ± .060 between the centers of the tabs, and a distance of 4.375 ± .060 from the end of the bar to the center of the right tab.</p>							
INSTRUCTIONS	Please check your stock ASAP and contact BPC Customer Service if you need replacement 16062279 pushbars.							