



NUMBER	16TSB-XX			TYPE	SERVICE/INSTALL ALERT			
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH	
TITLE	16071060/16073110 PACKAGING ERROR							
REV	A			ISSUED	10/31/2014	REVISED	-	
AFFECTS	16071060/16073110 SHIPPED BETWEEN 10/10/14 AND 10/31/14							
INFORMATION	<p>SOME 16071060 KITS (CONTAINING 16073110) WERE SHIPPED WITH THE 2X FEMALE H13 CONNECTORS MISSING. CHECK YOUR STOCK OF 16071060 ADAPTERS TO VERIFY THAT THE CORRECT CONNECTORS ARE PRESENT.</p> <p style="text-align: center;">WRONG CORRECT</p> <div style="display: flex; justify-content: space-around;">   </div>							
INSTRUCTIONS	<p>CONTACT CUSTOMER SERVICE AT 440-974-8888 FOR THE CORRECT PARTS. THE MISSING PART IS 16071064. THERE ARE 2 PER KIT</p> <p>CONTACT SNOWDOGGTECH@BUYERSPRODUCTS.COM WITH ANY QUESTIONS.</p>							