





TECHNICAL  
SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-101</b>			<b>TYPE</b>	<b>INFORMATION ONLY</b>			
<b>ROUTING</b>	INSTALL	<b>X</b>	SERVICE	<b>X</b>	SALES		PURCH	
<b>TITLE</b>	<b>SNOWDOGG SHOCK KIT</b>							
<b>REV</b>	-			<b>ISSUED</b>	<b>11/21/2022</b>		<b>REVISED</b>	
<b>AFFECTS</b>	<p align="center"><b>16101502 SHOCK KIT USED IN 16011006 HD/EX LIFT FRAME, 16017006 CM LIFT FRAME, 16019006 XP LIFT FRAME</b></p>							
<b>INFORMATION</b>	<p>Some shock kits in 16011006 HD/EX lift frame kits shipped after August 2022 were packed with the incorrect shock. The incorrect shock used does not have a steel bushing and the hole is too small for the 3/4" clevis pin included. <b>They cannot be used and should be replaced with 2x 16101502.</b></p> <p><b>CORRECT PART 16101502</b></p>  <p><b>INCORRECT PART</b></p> 							
<b>INSTRUCTIONS</b>	Assemble the plow without the shocks and contact your dealer or Buyers Products Customer Service to arrange to replace the incorrect components.							