SnowDogg						TECHNICAL SERVICE BULLETIN				
NUMBER	16TSB-105			TYPE		SERVICE ALERT				
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH			
TITLE	2023	3+ FOR	D SUPE	RDUTY				ISABLIN	IG ON TRUCK	
REV	-		ISSUED	8/31/2023		3	REVISED			
AFFECTS	16071340 HEADLIGHT ADAPTER									
INFORMATION	This is still being investigated by Ford. Some 2023 superduties do not have the high beam in the truck upfitter connector, so it cannot be disabled by the plow harness. The plow high beams work normally - but the truck high beams are not disabled.									
INSTRUCTIONS	Pending further information from Ford - use of plow high beams is not recommended in order to avoid potential glare from the rear of the plow. This TSB will be updated as soon as more information is available.									