



# TECHNICAL SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-58</b>			<b>TYPE</b>	<b>APPLICATION/INSTALL ALERT</b>			
<b>ROUTING</b>	INSTALL	<b>X</b>	SERVICE	<b>X</b>	SALES		PURCH	
<b>TITLE</b>	<b>16062115A MOUNT</b>							
<b>REV</b>	<b>A</b>			<b>ISSUED</b>	<b>1/10/2014</b>	<b>REVISED</b>	<b>-</b>	
<b>AFFECTS</b>	16062115A MOUNT							
<b>INFORMATION</b>	<p>The 16062115A MOUNT (REPLACES 16062115) MAY INTERFERE WITH CERTAIN 1500 TRUCK FRAMES. THE 16062115 MOUNT IS NOT AFFECTED BY THIS.</p>							
<b>INSTRUCTIONS</b>	<p>IF NECESSARY, REMOVE THE CIRCLED TABS AS SHOWN ON BOTH OUTER PS+DS SIDES. THIS WILL ELIMINATE THE INTERFERENCE. THE MOUNT HAS BEEN REDESIGNED TO ADDRESS THIS ISSUE.</p>							