




TECHNICAL  
SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-75</b>			<b>TYPE</b>	<b>SERVICE ALERT</b>			
<b>ROUTING</b>	INSTALL	<b>X</b>	SERVICE	<b>X</b>	SALES		PURCH	
<b>TITLE</b>	<b>G2 CHAIN LIFT</b>							
<b>REV</b>	<b>A</b>			<b>ISSUED</b>	<b>1/12/2018</b>	<b>REVISED</b>	<b>-</b>	
<b>AFFECTS</b>	<b>ALL G2 PLOWS, 1601X002/1601X022</b>							
<b>INFORMATION</b>	<p>Verify that the chains are correctly installed on all plows. Installation backwards can result in damage to the chainlift. Correct installation is shown below.</p> 							
<b>CORRECTION</b>	Install chains correctly and ensure that chain clip kit 16111410 is installed as shown.							