




TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-80			TYPE	SERVICE ALERT			
ROUTING	INSTALL	X	SERVICE		SALES		PURCH	
TITLE	2018 G2 MOLDBOARD TRIP TUBE							
REV	A			ISSUED	6/26/2018	REVISED	-	
AFFECTS	HD2/EX2/TE2 MOLDBOARDS (160205X2, 160206X2, 160203X2)							
INFORMATION	<p>Some moldboards shipped prior to 6/25 may have undersized trip tubes that will prevent assembly of the moldboard onto the lift frame sector.</p> 							
CORRECTION	<p>All moldboards can be checked with a standard 1" trip pin (PN 16101100). If the pin doesn't go all the way through then the moldboard should be warranteed through the normal process. Please contact your dealer or SnowDogg customer service with any questions.</p>							