



TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-82			TYPE	SERVICE ALERT			
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH	
TITLE	16071150/16071150R IDENTIFICATION							
REV	A			ISSUED	10/31/2018	REVISED	-	
AFFECTS	16071150 and 16071150R							
INFORMATION	As 16071150 and 16071150R are identical with the exception of pinout - this service alert includes pictures of both adapters to aid in identification.							
CORRECTION	<p>The only difference is in the LONG GRAY and BLACK connectors. 16071150R - the BLACK wires are in the B position 16071150 - the BLACK wires are in the A position</p> <p>In order to work properly, the LONG GRAY and BLACK connectors must match on both headlights. If any one of the 4 is not wired properly, the headlights will not function properly.</p>							