



# TECHNICAL SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-83</b>			<b>TYPE</b>	<b>SERVICE ALERT</b>			
<b>ROUTING</b>	INSTALL	<b>X</b>	SERVICE	<b>X</b>	SALES		PURCH	
<b>TITLE</b>	<b>2018 TOYOTA TUNDRA LED OPTIONS</b>							
<b>REV</b>	<b>A</b>			<b>ISSUED</b>	<b>10/31/2018</b>	<b>REVISED</b>	<b>-</b>	
<b>AFFECTS</b>	<b>2018 TOYOTA TUNDRA W/LED</b>							
<b>INFORMATION</b>	<p>The 2018+ Toyota Tundra with LED headlights will register a headlight fault when the plow lights are activated. <b>While the lights will function correctly</b>, it registers a fault on the dash display.</p>							
<b>CORRECTION</b>	<p>The installer has two options.</p> <ol style="list-style-type: none"> <li><b>Operate the plow as is</b>, ignoring the displayed headlight fault.</li> <li><b>Install SERVICE KIT 3041131</b>. This will keep the truck lights on with the plow lights and prevent the error from displaying. This is easily removed.</li> </ol> <p><i>Further options are being investigated and dealers will be notified if a plug and play solution is found to disable to the malfunction indicator.</i></p> <div data-bbox="574 1077 1338 1539" data-label="Image"> </div>							