TECHNICAL SERVICE BULLETIN

NUMBER	**16TSB-90**	***TYPE***	**INFORMATION**		
TITLE	**EYE BOLTS ON NEWER MD MOLDBOARDS**				
REV		***ISSUED***	**10/22/2020**	***REVISED***	**10/22/2020**
AFFECTS	All newer MD moldboards				
INFORMATION	Newer MD moldboards have a longer spring static length and are designed for use with full length eye bolts (#16101210) used on all other straight blade plows.				
IDENTIFICATION	The eyebolts are in the lift frame box, so when you go to assemble the springs to the moldboard you will have difficulty starting the nuts on the eybolts.				
INSTRUCTIONS	The soluton is to use the full-size eye bolts #16101210 instead of the #16101220. Please call customer service to get the right size eyebolts ordered and mention this TSB. Newer lift frame kits have the longer eye bolts - so this will be a short term issue.				