



SERVICE ALERT

16-TSB13

HARNESS RELAY MODULE INSTALLATION INSTRUCTION ERROR

APPLIES TO:

- HD/EX LIFT FRAME KIT (16011000)
- MD LIFT FRAME KIT (16015000)

The RELAY MODULE HARNESS (16160100) was recently upgraded to include an independent ground for the turn signal relays. This is a black wire (in addition to the red and orange wires).

Some plows were shipped with older instructions that do not mention this wire.

1. Install the harness as directed.
2. Connect the black wire to ground. Failure to ground the black wire will result in the plow turn signals not functioning but will not cause damage to any components in the plow or vehicle.

We apologize for the inconvenience.