



TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-84			TYPE	SERVICE ALERT			
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH	
TITLE	HEADLIGHT INSTALLATION/HARDWARE							
REV	A			ISSUED	11/5/2018	REVISED	-	
AFFECTS	ALL SNOWDOGG PLOWS - 16160700 LIGHT KIT							

INFORMATION

Some 2018 SnowDogg lift frame kits were shipped with incorrect light mounting hardware. The correct hardware is shown below.

- Bolts with the thread length too short making it impossible to securely tighten the light hardware.
- Kits containing NYLOCK nuts. In some cases this would cause the bolts to spin in the light housing making tightening impossible.

CORRECTION

IN all cases, NYLOCK nuts should be replaced with standard nuts to allow proper assembly. 1/2-13 hex nut - available as FNH050013041SS

If the thread length is too short, washers/spacers may be added to allow proper tightening.

With the current light hardware kit - the fender washer **MUST** be used to properly compress the lower rubber spacer.

The light hardware kit has been renamed to 16160730A - one is required for each light.

