




TECHNICAL SERVICE BULLETIN

NUMBER	SD-TSB-061726			TYPE	INFORMATIONAL ONLY				
ROUTING	INSTALL	X	SERVICE	X	SALES	X	PURCH	X	
TITLE	DESIGN CHANGE: MATERIAL FEED GATE REMOVAL ON ELECTRIC CONVEYOR SPREADERS								
REV	A			ISSUED	6/17/2026		REVISED		
MAY AFFECT	1400601SS, 1400801SS PRO SST ELECTRIC CONVEYOR SPREADERS 147XX FXX0211 MIDSIZE ELECTRIC CONVEYOR SPREADERS								
INFORMATION	<p>The rear adjustable gate has been removed from SaltDogg electric conveyor spreaders for the 2026 season. Since the feed and spinner are separately adjustable, it was found in testing that the feed gate served no purpose, and in some cases caused problems as users would have it set too low. The parts affected are shown in red below. Feed speed should be controlled by the motor speed.</p> <p>The mounting studs will remain in place as the same hopper weldment is used for gas spreaders</p> <div style="text-align: center;">  </div>								
INSTRUCTIONS	<p>No action is required. This is informational only. For users that insist on having a feedgate - the complete kit shown above is available as service part 3079735 for PRO SST spreaders and 3079736 for MIDSIZE spreaders.</p>								