



## TECHNICAL SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-29</b>	<b>TYPE</b>	<b>INSTALLATION ALERT</b>		
<b>TITLE</b>	<b>GM 4500/5500 MOUNT (4X4)</b>				
<b>REV</b>	<b>A</b>	<b>ISSUED</b>	<b>10/7/2009</b>	<b>REVISED</b>	-
<b>AFFECTS</b>	GM C4500/C5500 4WD (4X4) TRUCKS 16062400 MOUNT KIT				
<b>INFORMATION</b>	THE 16062400 MOUNT KIT DESIGNED FOR GM C4500/C5500 TRUCKS MAY NOT WORK WITH 4WD (4X4) VEHICLES. THE SPRING HANGER ON THE PASSENGER SIDE INTERFERES WITH THE SIDE PLATE.				
<b>IDENTIFICATION</b>	GMC C4500/C5500 4WD (4X4) TRUCK WITH A SPRING HANGER ON THE OUTSIDE OF THE PASSENGER SIDE FRAME				
<b>INSTRUCTIONS</b>	THIS MOUNT WILL NO LONGER BE OFFERED FOR THE 4WD APPLICATION. THE APPLICATION WILL BE REVIEWED FOR FUTURE DEVELOPMENT.				