

SnowDoggby **Buyers****TECHNICAL
SERVICE BULLETIN**

NUMBER	16TSB-62			TYPE	SERVICE/INSTALL ALERT			
ROUTING	INSTALL	X	SERVICE		SALES		PURCH	
TITLE	MOLDBOARD TRIP TUBES							
REV	A			ISSUED	11/9/2015		REVISED	-
AFFECTS	SOME SNOWDOGG HD/EX/TE/XP MOLDBOARDS SHIPPED BEFORE 9/22/15							
INFORMATION	<p>SOME TRIP PIN TUBES OF THE WRONG ID WERE USED IN MOLDBOARD WELDMENTS. THE TRIP PINS WILL NOT FIT INTO THESE MOLDBOARDS MAKING PLOW ASSEMBLY IMPOSSIBLE. THESE COMPLETE MOLDBOARD ASSEMBLIES SHOULD BE WARRANTEED AND REPLACED.</p> <p>EXISTING STOCK SHOULD BE CHECKED WITH A TRIP PIN ON BOTH SIDES.</p> <p>QUANTITIES AFFECTED SHOULD BE SMALL - BUT PLEASE CHECK STOCK AND ARRANGE REPLACEMENTS TO AVOID A PROBLEM AT INSTALLATION.</p>							
DETECTION	AT PLOW ASSEMBLY - CONNECTION OF MOLDBOARD TO SECTOR							
CORRECTION	<p>CONTACT CUSTOMER SERVICE AT 440-974-8888 FOR REPLACEMENT OF MOLDBOARDS AFFECTED.</p> <p>CONTACT SNOWDOGGTECH@BUYERSPRODUCTS.COM WITH ANY QUESTIONS.</p>							