

SnowDoggby **Buyers****TECHNICAL
SERVICE BULLETIN**

NUMBER	16TSB-26	TYPE	INSTALLATION ALERT		
TITLE	CONTROL HARNESS FUSE SIZE				
REV	A	ISSUED	9/16/2009	REVISED	-
AFFECTS	16160300 CONTROL HARNESSES SHIPPED PRIOR TO 9/1/09 - ONLY ON SWITCHED GROUND VEHICLES WHERE GRAY WIRE IS USED TO POWER HEADLIGHTS.				
INFORMATION	IN SOME APPLICATIONS, THE 5A STANDARD FUSE ON THE 16160300 HARNESS MAY NOT BE ADEQUATE AND MUST BE REPLACED WITH A 10A FUSE. THIS IS TYPICALLY ONLY AN ISSUE ON TRUCKS WITH SWITCHED GROUND INSTALLATIONS, WHERE THE HEADLIGHT POWER IS SUPPLIED THROUGH THIS FUSE. HARNESSES SHIPPED AFTER 9/1/09 HAVE A 10A FUSE STANDARD.				
IDENTIFICATION	AFTER INSTALLATION, PLOW LIGHTS WORK BRIEFLY, AND THEN TURN OFF. CONTROLLER ALSO LOSES POWER.				
INSTRUCTIONS	REPLACE THE 5A FUSE WITH A 10A FUSE				