

TECHNICAL SERVICE BULLETIN

by Buyers www.			SERVICE BULLETIN						
NUMBER	SD-TSB-010224		TYPE					INSTALL ALERT	
ROUTING	INSTALL X	SERVICE		SALES		PURCH			
TITLE	TGS02 FORMED FRAME DS/PS FRAME PARTS								
REV			ISSUED	1	/2/2024		REVISED		
MAY AFFECT	TGS02 SPREADERS SHIPPED BETWEEN 3/3/2023 AND 9/13/2023 WITH FORMED FRAMES (SMALLER 22x18x31 BOX)								
INFORMATION	Some initial shipments of TGS02 spreaders with the formed frame may have shipped with incorrect parts. The kits should have a Passenger and Driver mount plate. PN's 3055127 and 3055130 shown below. All stock was audited and corrected on 9/13/2023. This only impacts TGS02's in the newer/smaller 22x18x31 boxes.								
INSTRUCTIONS	Inspect TGS02 stock and contact Customer Service for correct parts as required. 3055127 is the DRIVER SIDE MOUNT 3055130 is the PASSENGER SIDE MOUNT								

SD-TSB-010224.xlsx