



TECHNICAL
SERVICE BULLETIN

NUMBER	16TSB-108			TYPE	APPLICATION ALERT			
ROUTING	INSTALL	X	SERVICE	X	SALES		PURCH	
TITLE	16071350 H9/H11 Toyota Tacoma 2016+ Adapter Instructions							
REV	-			ISSUED	10/24/2023		REVISED	
AFFECTS	16071350 Headlight Adapter for H9/H11 Bulbs - Toyota Tacoma 2016+							
INFORMATION	<p>The instructions for 16071350 omitted a section on necessary modifications to the adapter.</p> <ul style="list-style-type: none"> - Removing the tab is necessary to connect to vehicle harness. - The pins MAY need to be swapped to match GROUND to GROUND. Failing to do this will prevent the adapters from working properly. <div style="text-align: center;"> <p>REMOVE COMPLETE PLASTIC TAB</p> </div> <p>Note: Due To Manufacturing Variations on Toyota vehicles, it may be necessary to reverse the polarity (Swap the A+B pins) of the adapters on the side that connects to the vehicle harness as shown. Proper orientation is as follows: When installed, the BLACK wire on the 16071350 adapters should mate with the WHITE/BLACK wire of the vehicle headlight harness.</p>							
INSTRUCTIONS	See the above instructions to rework at the time of installation. All 16071350 adapters in stock as of 10/12/2023 will ship with the tabs and keys removed to allow reversal of polarity without disassembly.							