



TECHNICAL SERVICE BULLETIN

NUMBER	16TSB-32	TYPE	INSTALLATION ALERT		
TITLE	DODGE 94-02 2500/3500 INSTALLATIONS MOUNT 16063400				
REV	A	ISSUED	10/15/2009	REVISED	-
AFFECTS	SOME 94-02 DODGE 2500/3500 INSTALLATIONS USING MOUNT 16063400				
INFORMATION	THE EXISTING 16063400 MOUNT MAY INTERFERE WITH THE STEERING KNUCKLE AT END OF STROKE AND MAY NOT ALLOW THE PLOW TO BE MOUNTED LOW ENOUGH ON THE VEHICLE (TO LEVEL THE A-FRAME)				
INSTRUCTIONS	THE MOUNT REAR BRACES HAVE BEEN REDESIGNED TO ACCOMMODATE THE 2500/3500'S AFFECTED. ALL STOCK HAS BEEN REWORKED. THE DEALER MAY, AT THEIR OPTION, CONTACT SNOWDOGG TECH SUPPORT FOR REWORK INSTRUCTIONS OR ARRANGE FOR NEW HARDWARE.				