



## TECHNICAL SERVICE BULLETIN

<b>NUMBER</b>	<b>16TSB-56</b>			<b>TYPE</b>	<b>APPLICATION ALERT</b>			
<b>ROUTING</b>	INSTALL	<b>X</b>	SERVICE	<b>X</b>	SALES	<b>X</b>	PURCH	<b>X</b>
<b>TITLE</b>	<b>GM 2014 1500 TRUCK APPLICATION</b>							
<b>REV</b>	<b>A</b>			<b>ISSUED</b>	<b>9/26/2013</b>	<b>REVISED</b>	<b>10/8/2013</b>	
<b>AFFECTS</b>	16062115A/16062102A							
<b>INFORMATION</b>	<p>DUE TO UNEXPECTED CHANGES IN THE GM BUMPER ON THE 2014 1500'S - THE 16062102A AND 16062115A MOUNTS CAN NO LONGER BE USED ON THE 2014 1500'S.</p> <p>THESE MOUNTS ARE STILL ABLE TO BE USED ON 2007-2013 1500'S.</p> <p>IT IS NOT POSSIBLE TO MODIFY THE MOUNT TO WORK. A NEW MOUNT IS BEING DEVELOPED ASAP AND NOTIFICATION WILL BE SENT WHEN IT IS AVAILABLE.</p>							
<b>INSTRUCTIONS</b>	<p>16062140 AND 16062145 (MD/VMD) ARE CURRENTLY IN DEVELOPMENT AND WILL BE RELEASED AS QUICKLY AS POSSIBLE. THE EXISTING MOUNTS ARE STILL VALID FOR 2007-2013 1500'S. CONTACT CUSTOMER SERVICE TO PLACE ORDERS FOR THE NEW MOUNT.</p> <p>THE 5562112 LEVELING KIT MAY BE USED WITH THE 16062140/16062145 TO ALLOW FOR INSTALLING THE MOUNT WITHOUT CUTTING THE BUMPER.</p>							